



TOTAL DOOR
(In project documents)



ALTERNATIVE DOOR
(Not in project documents)

See page 2 for description of each door



TOTAL DOOR (In project documents)

- Meets all smoke testing requirements and has a testing report for the entire system
- Underwriters Laboratory and Warnock Hershey with a UL 10C Positive Pressure Fire Label
- Single source manufacture for entire system
- Entire system has been tested to 5 million cycles without failure
- All hardware is factory installed and shipped as a system with no field assembly required
- Life time warranty on all hardware
- 35 years manufacturing experience and Total Doors are in some of the most prestigious buildings in the world
- Door system is completely flush with the wall in the pocketed position
- No exposed screws on the door
- No floor penetrations or thresholds needed to meet code
- Custom factory painted with a durable baked on two part polyurethane paint to match the specified color



ALTERNATIVE DOOR (Not in project documents)

- Does not meet smoke testing requirements and has no testing report for the entire system
- Fire testing procedure and label unknown
- Various manufactures with all parts field assembled
- Door is not manufactured as a system and has no system cycle test
- Heavy field installation required to install all hardware
- No life time warranty on hardware
- Exposed vertical rods, hinge knuckles, coordinators, astragals, flush bolts
- Door does not site flush in the pocket
- Maintenance issues because of exposed hardware and various manufactures
- Panics are not flush
- Multiple exposed screws and bolts
- Threshold or floor penetration need in order to meet fire code
- Field painted door and hardware cannot be painted to match door and wall